

AMENDMENTS TO THE DRAWINGS

The attached sheets of drawings include replacement sheets for Figs. 1, 3, 4 and 7-10 to replace original Figs. 1, 3, 4 and 7-10. The Examiner indicated that the character lines, numbers and letters are pale in parts. The replacement sheets address this problem.

Enclosures:

Replacement Sheets

Application No. 09/473,683

Confirmation No. 1308

Applicant: Stephen Palm

Attorney Docket No. P1

Title: ACTIVATION OF MULTIPLE xDSL MODEMS WITH HALF DUPLEX AND
FULL DUPLEX PROCEDURES

Responsive to Official Communication dated: August 19, 2003
REPLACEMENT SHEET






FIG. 1



$\tau_1 < 500$ msec.

50 msec. $< \tau_2 < 500$ msec.

FIG. 3



$\tau_1 < 500$ msec.

FIG. 4




FIG. 7

Application No. 09/473,683

Applicant: Steven Palm

Title: ACTIVATION OF MULTIPLE xDSL MODEMS WITH HALF DUPLEX AND
FULL DUPLEX PROCEDURES

Responsive to Official Communication dated: August 19, 2003
REPLACEMENT SHEET




FIG. 8





FIG. 9

Application No. 09/473,683 Confirmation No. 1308
Applicant: Steven Palm Attorney Docket No. P1806
Title: ACTIVATION OF MULTIPLE xDSL MODEMS WITH HALF DUPLEX AND
FULL DUPLEX PROCEDURES
Responsive to Official Communication dated: August 19, 2003
REPLACEMENT SHEET



$\tau_1 < 500$ msec.

FIG. 10